

Thermal Environment

Recommendations for Temperature

Type of Work	Temperature
Light Work	Between 66°F and 79°F
Moderate Work	Between 64°F and 74°F
Heavy Work	Between 60°F and 68°F
Humidity	Between 20% and 85%